

205090 2854001




FIG. 1 (prior art)




FIG. 2 (prior art)




FIG. 3 (prior art)




FIG. 4




FIG. 5

2004597-0000




FIG. 6

700





FIG. 7

FIG. 8



205090" 4854001




FIG. 9



### Intra-node Fiber Fault Handling

Legend	AS	Reg Switch
DRS	Reg Switch Drive, n	
EO	Equivalent Switch, n	
DO	Equivalent Switch Drive, n	
LOS	Loss of Signal at Receiver (n)	

(b) *Referred to the Committee on the Judiciary, Subcommittee on the Constitution, for a report by the end of the 100th Congress.*

FIG. 10a

[illegible]

[illegible]

/

205090" 2855400T




FIG. 11




FIG. 12




FIG. 13

205090 7255400T




FIG. 14




FIG. 15




FIG. 16




FIG. 17








FIG. 18






FIG. 21




FIG. 22




FIG. 23




FIG. 24

205090" 2855400T




FIG. 25




FIG. 26